


N05: douille de centrage

exemple de commande:

1 pièce N05 Ø14/20




matière: 1.7139 ~ 700HV

L1	M	d	D	L	
8	8	11	14	20	•
				30	•
				40	•
				50	•
				60	•
				70	•
				80	•
				100	•
12	12	16	20	30	•
				40	•
				50	•
				60	•
				70	•
				80	•
				100	•
				120	•
				140	•
				160	•
12	12	21	26	30	•
				40	•
				50	•
				60	•
				70	•
				80	•
				100	•
				120	•
				140	•
				160	•
				180	•
12	12	25	30	40	•
				50	•
				60	•
				80	•
				100	•
				120	•
				140	•
				160	•
				180	•
				200	•
				220	•
				240	•

N05: douille de centrage

exemple de commande:

1 pièce N05 Ø42/40



matière: 1.7139 ~ 700HV

L1	M	d	D	L	
12	12	33	42	40	•
				60	•
				80	•
				100	•
				120	•
				140	•
				160	•
				180	•
				200	•
				220	•
				240	•
				260	•
				280	•
				300	•
12	12	43	54	60	•
				80	•
				100	•
				120	•
				140	•
				160	•
				200	•
				240	•
				280	•
				320	•
18	20	54	66	80	•
				100	•
				120	•
				140	•
				160	•
				180	•
				200	•
				240	•
				280	•
				320	•
18	20	64	80	100	•
				120	•
				140	•
				160	•
				200	•
				240	•
				280	•
				320	•