


N25: Bride de centrage avec perçage

exemple de commande:

1 pièce N25 Ø125/



LK= cercle de perçage

matière: 1.1191



S	LK1	d	D	H	
-	104	82	125	12	•
6				18	•
8				20	•
-	144	120	160	14	•
6				20	•
8				22	•

S	LK1	d	D	H	
-	144	120	200	14	•
8				22	•
-	144	120	250	14	•
8				22	•

N26: Bride de centrage avec perçage

exemple de commande:

1 pièce N26 Ø60/90/18



LK= cercle de perçage

matière: 1.1191

I1	I2	S	LK1	d	D1	D	H	
8	10	-	75	50	60	90	18	•
		6					24	•
		8					26	•
4	8	-	98	82	110	90	12	•
		6					18	•
		8					20	•
4	8	-	104	82	120	90	12	•
		6					18	•
		8					20	•
4	8	-	104	82	125	90	12	•
		6					18	•
		8					20	•
4	8	-	104	82	160	90	12	•
		6					18	•
		8					20	•

I1	I2	S	LK1	d	D1	D	H	
4	8	-	104	82	175	90	12	•
		6					18	•
		8					20	•
8	10	-	95	70	80	110	18	•
		6					24	•
		8					26	•
4	10	-	144	120	175	160	14	•
		6					20	•
		8					22	•
4	10	-	144	120	200	160	14	•
		8					22	•
4	10	-	144	120	250	160	14	•
		8					22	•